






STANDPIPE ROAD DETOUR ROUTE

PETTIGREW & ASSOCIATES PA
 ENGINEERING | SURVEYING | TESTING
 DEFINING QUALITY SINCE 1965
 100 E. Navajo Drive Suite 100 Hobbs New Mexico 88240
 T 575 393 9827 F 575 393 1543
 Pettigrew.us



-  NORTH BOUND DETOUR ROUTE
-  SOUTH BOUND DETOUR ROUTE
-  PHASE I
-  PHASE II

